Maryland Historical Trust

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in

Maryland Inventory of Historic Properties Number:

February 2001. The Trust accepted the received the following determination of	e Historic Bridge Inventory on April 3, 2001. The bridged feligibly.
MAR'	YLAND HISTORICAL TRUST
Eligibility Recommended	Eligibility Not RecommendedX
Criteria:ABCD	Considerations:ABCDEFG _None
Comments:	
	
Reviewer, OPS:Anne E. Bruder	Date:3 April 2001
Reviewer, NR Program:_Peter E. Kurtze	Date:3 April 2001

14h

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

NAME AND SHA NO.: 8028

LOCATION LN L. MD 227 and Matteryomen Creek	
Road Name and Number: MD 227 over Mattawoman Creek City/Town: Mattawoman Natural Environmental Area X vicinity County: Charles	
Ownership: X State County Municipal Other	
Bridge projects over: _ Road _ Railway X Water _ Land	
Is bridge located within designated district?: _ yes X no NR listed district _ NR determined eligible district locally designated _ other Name of District _	
BRIDGE TYPE	
Timber Bridge Beam Bridge Truss-Covered Trestle Timber-and-Concrete	
Stone Arch Bridge	
Metal Truss Bridge	
Moveable Bridge Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon	
Metal Girder Rolled Girder Rolled Girder Concrete Encased Plate Girder Plate Girder Concrete Encased	
Metal Suspension	
Metal Arch	
Metal Cantilever	
X Concrete Concrete Arch Other Concrete Slab X Concrete Beam Rigid Frame Type Name 437	

MARYLAND INVENTORY OF HISTORIC PROPERTIES
HISTORIC BRIDGE INVENTORY
MARYLAND STATE HIGHWAY ADMINISTRATION
MARYLAND HISTORICAL TRUST

DESCRIPTION

Describe the Setting:

Bridge 8028 carries MD 227 (Pomfret Road) over Mattawoman Creek in the Mattawoman Natural Environmental Area of Charles County. MD 227 runs in a generally north-south direction at this location; Mattawoman Creek flows east-west. The area is very rural and heavily wooded. No buildings are visible from the bridge. Bridge 8028 is located within the Tidewater physiographic province which features mainly flat or gently undulating terrain crossed by tidal rivers and streams.

Describe the Superstructure and Substructure: (Discuss points identified in Context Addendum, Section C)

Bridge 8028 is a triple-span concrete girder bridge measuring 93' in total length. Each span is 30' long and the clear roadway, which carries two lanes of traffic, measures 24' wide with 4.5" high parapets on either side. The solid concrete parapets include five panels, alternating rectangles and squares, per span. Metal W-beam guardrails are attached to the ends of each parapet. The superstructure of the bridge consists of concrete abutments, concrete wing walls and two concrete piers. The solid shaft piers each measure 2'-6" wide and have a pointed nose upstream. Piles support the abutments and piers.

Bridge inspection reports from the late 1970s through the 1990s indicate that the bridge shows signs of spalling and cracking of the deck, abutments, wing walls and beams. As-built drawings from November 1990 illustrate the underpinning of the north end of pier 1 through the placement of grout bags and rip rap around the pier. Recent inspection reports also mention the repair of deteriorated concrete girders with pneumatically applied mortar and the installation of new scuppers.

A survey of historic concrete beam bridges undertaken by the Maryland State Highway Administration in the Fall of 1995 identified 113 bridges of that type located throughout the state. Nine percent (10) of that total were triple-span bridges; 37 bridges (33%) were multiple span.

Discuss major alterations:

Since the construction of this bridge, the structure has not received any major alterations.

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

HISTORY

When Built: 1930

Why Built: Statewide road improvement programs and local transportation needs

Who Built: De Luca Construction Company, Dundalk, Maryland

Who Designed: Unknown Why Altered: Unknown

Was this bridge built as part of an organized bridge building campaign?: N

This bridge was built during the Good Roads Movement era but was not one of the primary corridors slated for improvement.

SURVEYOR ANALYSIS

This bridge may have NR significance for association with:

_ A (Events) _ B (Person) _ C (Engineering/Architectural Character)

Was this bridge constructed in response to significant events in Maryland or local history?

The improvement of Charles County roads most likely resulted from several events that occurred during the first three decades of the twentieth century. The original Good Roads movement was aimed toward improving the primary routes through the state as well as connecting roads between counties. A later impact of this crusade included the widening, straightening, and grading of secondary roads, and construction of new bridges to carry these rebuilt roads. Further, the rapid increase of automobile, truck, and bus traffic prompted the replacement of the existing narrow and weak bridges with new, wider, and stronger concrete structures. As time, labor, and money-saving plans created by the State Roads Commission (SRC), the establishment of district engineering offices during the 1910s and the development of standardized bridge designs also aided in the construction of modern bridges throughout the state. During the 1920s, emphasis of the SRC was on improving safety and comfort of main routes while building up the secondary roads and the farm-to-market network of feeder roads. By the 1930s, bridges believed to be adequate when initial road reconstruction was undertaken became unacceptable for modern traffic and many new structures were constructed.

When the bridge was built, and/or given a major alteration, did it have a significant impact on the growth and development of the area?

No, the construction of this bridge did not play an active role in the growth or development of this portion of Charles County.

439

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

Is the bridge located in an area which may be eligible for historic designation, and would the bridge add or detract from the historic and visual character of the possible district?

No, this bridge is not located within an area which is eligible for historic district designation.

Is the bridge a significant example of its type?

Yes, due to its apparent lack of major alterations and fair condition, this bridge stands as a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Yes, this bridge retains integrity of its character defining elements. Although recent reports indicate that the structure exhibits signs of age and wear, including cracking and spalling of the parapets, abutments, and wing walls, none of these character defining elements has been replaced or removed.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer, and why?

This bridge may be a significant example of the work of the manufacturer, designer, and/or engineer due to its used of long specification concrete beams.

Should this bridge be given further study before significance analysis is made, and why?

According to an earlier survey form completed in 1995, this bridge contains long specification concrete beams and should be compared with other local examples, including CH-35.

BIBLIOGRAPHY

Crosby, Walter Wilson

1906 First Report on State Highway Construction (May 1905-January 1906). The Johns Hopkins Press, Baltimore.

1908 Second Report on State Highway Construction (January 1906-January 1908). The Johns Hopkins Press, Baltimore.

Date: 13 May 1996

Telephone: (717) 691-1340

MARYLAND INVENTORY OF HISTORIC PROPERTIES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION MARYLAND HISTORICAL TRUST

Johnson, A.N.

1903 Third Report on the Highways of Maryland (1902-1903). The Johns Hopkins Press,

Baltimore.

LeViness, Charles T.

1958 A History of Road Building in Maryland. State Roads Commission of Maryland,

Baltimore.

Maryland State Highway Administration

As-built drawings. Located in the files of the Office of Bridge Development,

Maryland State Highway Administration, Baltimore.

1987-93 Bridge inspection reports. Located in the files of the Office of Bridge Development,

Maryland State Highway Administration, Baltimore.

P.A.C. Spero and Company and Louis Berger and Associates, Inc.

1994 Historic Bridges in Maryland: Historic Context Report. Prepared for Maryland State

Highway Administration, Maryland State Department of Transportation, Baltimore.

State Roads Commission of Maryland

1930 Reports of the State Roads Commission of Maryland for the Years 1927, 1928, 1929,

and 1930. State of Maryland, State Roads Commission, Baltimore.

1931-79 Bridge inspection reports. Located in the files of the Office of Bridge Development,

Maryland State Highway Administration, Baltimore.

SURVEYOR INFORMATION

Name: Organization:


Margaret A. Bishop and Michelle M. Lupien

KCI Technologies, Inc.

Address:

5001 Louise Dr., Suite 201

Mechanicsburg, PA 17055





CH-383
CHARLES COUNTY, MD
TIM BATCHER
8 FEB 1995
MARYLAND SHPO SHA
BRIDGE NO. 8028 OVER MATTAWOMEN CREEK
VIEW LOOKING EAST ALONG RT. 227

1/4



CH-383
CHARLES COUNTY, MD.
TIM BATCHER
8 FEB 1995
MARYLAND SHPO SHA
BRIDGE NO. 8028 OVER MATTAWOMEN CREEK
VIEW LOOKING SOUTH



CH-383

CHARLES COUNTY, MD

TIM BATCHER

8 FEB 1995

MARYLAND SHPO S HA

BRIDGE HO. 8028 OVER MATTAWOMEN CR.
VIEW LOOKING WEST ALONG RT 227



CH-383
CHARLES COUNTY, MD.
TIM BATCHER
8 FEB 1995
MARYLAND SUPO S HA
BRIDGE HO. 8028 OVER MATTAWOMEN CREEK
VIEW LOOKING HORTH

4/4